Printed on: 5/15/2009 12:26:05 AM

National Transportation Safety Board	NTSE					Aircraft Registration Number: N83086 Most Critical Injury: None			
FACTUAL REPORT	Occu								
AVIATION	Occu	rrenc	e Type: Accid	lent	Investigated By: NTSB				
Location/Time									
Nearest City/Place	State Zi		Code Local Time		Time Zone				
St. Maarten				1148	AST				
Airport Proximity: Off Airport/Airstrip	Distance Fro	m La	inding Facility:	•					
Aircraft Information Summary									
Aircraft Manufacturer		Model/Series	5		Type of Aircraft				
BELL		206B			Helicopter				
Revenue Sightseeing Flight: Yes	Air Medical Transport Flight: No								

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 4, 2009, at 1148 Atlantic standard time, a Bell 206B helicopter, N83086, was substantially damaged during a forced landing near Phillipsburg, Saint Maarten, Netherlands, Antilles. The pilot and 2 passengers were not injured. Visual meteorological conditions prevailed for the local sightseeing flight.

According to information released by the Directorate of Civil Aviation, the helicopter was maneuvering when the pilot noticed a loss of altitude and a corresponding decrease in engine and rotor rpm. The pilot entered autorotation, and maneuvered the helicopter towards the beach. During the descent, he noted that the "engine out" caution light was illuminated. As he approached the landing area, the pilot observed that the beach was crowded, and elected to land in the water. The helicopter landed upright in shallow water, but was subsequently upset by the surf.

The accident occurred in the vicinity of 18 degrees, 02 minutes north latitude, 63 degrees, 06 minutes west longitude.

This investigation is under the jurisdiction of the Government of Netherlands Antilles. Any further information pertaining to this accident may be obtained from:

Directorate of Civil Aviation (Ministry of Communications) Seru Mahuma z/n Curacao, Netherlands Antilles

Tel: (599-9) 839 3333 Fax: (599-9) 868 9924

This report is for informational purposes and contains only information released by the Government

Updated on Mar 18 2009 3:44PM

of Netherlands Antilles.

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ERA09WA183

Occurrence Date: 03/04/2009

AVIATION Occurrence Type: Accident													
Landing Facility/Approach Inf	formation					<u> </u>							
Airport Name		Airp	oort ID:	Airport Elevation	n Rur	nway Used	Runwa	ay Lengt	h F	Runway Width			
l'				Ft. MS	SL N/	Α							
Runway Surface Type:													
Runway Surface Condition:													
Approach/Arrival Flown: NONE	Ē												
VFR Approach/Landing: Forced La	anding												
Aircraft Information													
Aircraft Manufacturer BELL			Model/ 206B					Serial 914	Number	lumber			
Airworthiness Certificate(s): Norm	———— ıal												
Landing Gear Type: Skid			T										
Amateur Built Acft? No	Number of Seats:			d Max Gross Wt.	1				ines: 1				
Engine Type:			Engine Manufacturer: Model/Series: 250-C20 SER					Rated Power: 420 HP					
- Aircraft Inspection Information													
Type of Last Inspection		Dat	te of Las	st Inspection	Time Si	ince Last Insp	ection		e Total Time				
							Но	Hours					
- Emergency Locator Transmitter (F	ELT) Information												
ELT Installed?/Type Yes / Unkno	wn	EL.	ELT Operated? No ELT Aided in Locating Accident Site?						? No				
Owner/Operator Information													
Registered Aircraft Owner			Street Address 227 MARINERS WAY										
BELL 206 INC			City	State									
		\longrightarrow	2:	BEAR					DE	19701-2295			
Operator of Aircraft			Street Address 227 MARINERS WAY										
BELL 206 INC		[City							Zip Code			
			BEAR Designator Code:							19701-2295			
Operator Does Business As:					perator Design	nator Co	ode:						
- Type of U.S. Certificate(s) Held: N Air Carrier Operating Certificate(s):													
All Carrier Operating Certificato(3).													
Operating Certificate:				Operator Cert	ificate:								
Regulation Flight Conducted Under	r: Non-U.S., Non-	Commerci	ial										
Type of Flight Operation Conducted	d: Other Work Use	e											
		FACTUAI	L REPO	ORT - AVIATION	1					Page 2			

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA183

Occurrence Date: 03/04/2009

AVIATI	Occurren	Occurrence Type: Accident													
First Pilot Information			'												
Name					City State					ite	Date of	of Birth	Age		
On File															
Sex: M Seat Occupied	: Right	С	Occupational Pi	lot?	Certificate Number: On File										
Certificate(s):					•										
Airplane Rating(s):															
Rotorcraft/Glider/LTA: Helic	copter														
Instrument Rating(s):															
Instructor Rating(s):															
Current Biennial Flight Revie	ew?														
Medical Cert.: Medical Cert. Status:							Date of Last Medical Exam:								
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night Instrum		Instrume	ent Simulated		Rotorcraft		Glider			
Total Time															
Pilot In Command(PIC)															
Instructor															
Instruction Received															
Last 90 Days															
Last 30 Days															
Last 24 Hours															
Seatbelt Used? Yes	Shou	ılder Harne:	ss Used? Yes			Toxicology Performed? Second Pilot? No									
Flight Plan/Itinerary															
Type of Flight Plan Filed: Ut	nknown														
Departure Point						State Airpor		port Identifier		Departure Time		Time Zor	ne		
St. Maarten									ΓFFG						
Destination						State Airport Identifier				er					
Local Flight						TFFG									
Type of Clearance: Unkno	wn														
Type of Airspace: Unkno	wn														
Weather Information															
Source of Wx Information:															
Interne	et														
FACTUAL REPORT - AVIATION										Page	2				

National Transportation Safety Board FACTUAL REPORT

NTSB ID: ERA09WA183

Occurrence Date: 03/04/2009

AVIATION			Occurrent	Occurrence Type: Accident								
Weather	Information											
WOF ID	Observation Time	Time Zone	WOF Elevation WOF Distance From Acci			n Accid	dent Site		Direction From	m Accident Sit	е	
TNCM	1200	AST	20 Ft	20 Ft. MSL				NM		Deg. Maç		. Mag.
Sky/Lowes	st Cloud Condition: Scatt				2000 Ft. AG	GL	Condition of					
Lowest Cei	iling: None	Ft.	AGL	Visibi	ility:	6	SM Altimeter:			30.03	"Hg	
Temperatu	ıre: 26 °C [Dew Point:	20 °C	Weath	ner Condit	tions at Acc	ident S	ite: Visual (Cond	litions		
Wind Direc	ction: 130	Wind Speed:	: 10		Winc	d Gusts:						
Visibility (R	RVR): Ft.	Visibility (RV	/V)	SM								
Accident	Information											
Aircraft Dar	mage: Substantial		Aircraft Fir	Aircraft Fire: None					olosio	n None		
- Injury Sur	mmary Matrix	Fatal Ser	rious Mino	or	None	TOTAL						
First Pil	lot				1	1]					
Second	d Pilot]					
Student	at Pilot						1					
Flight Ir	nstructor						1					
Check F	Pilot						1					
Flight E	Engineer]					
Cabin A	Attendants]					
Other C	Crew]					
Passen	ngers				2	2	[
- TOTAL A	ABOARD -				3	3]					
Other G	Ground						1					
- GRAND	O TOTAL -				3	3	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: ERA09WA183

Occurrence Date: 03/04/2009

Occurrence Type: Accident

Αc	lmi	inis	trativ	⁄e In	for	matior	۱

Investigator-In-Charge (IIC)

Brian C. Rayner

Additional Persons Participating in This Accident/Incident Investigation:

Michael Llanes Directorate of Civil Aviation Netherlands Antilles Seru Mahuma,